



P8.1

W1) FOOD SERVICE EQUIPMENT CONTRACTOR TO RUN HARD COPPER DRAIN LINE A' HIGH AS POSSIBLE FROM EVAPORATOR COIL TO INSIDE WALL THEN DOWN ON A SLOPE TO A POINT AS CLOSE AS POSSIBLE TO FLOOR THEN EXTEND THRU WALK-IN WALL FORMING A "P" TRAP FLAT AGAINST OUTSIDE WALK-IN WALL, THEN EXTEND TO FLOOR DRAIN. ALL LINES TO BE STRAPPED IN A NEAT MANNER. WRAP WITH FROSTEC HEAT TAPE AND WIRE FOR CONTINUOUS "ON" OPERATION. INSULATE WITH 1/2" THICK ARMAFLEX AND SECURE TO WALL. SEAL ALL PENETRATIONS.

