ARKANSAS DEPARTMENT OF LABOR AND LICENSING HVAC/R SECTION INSPECTION / VIOLATION REPORT

			a ,	
Date: October 23, 20			County:	
HVACR Contractor:	Comfort Systems USA			ic. # 0090325
Address:		Ph. #		
Owner: UALR Ph. #				
Location of Building: 333 President Clinton Ave.				
Type of Inspection	Underground	Rough-In	X	Final
	Complaint	Investigation		Re-Inspection
V Satisfactory X Unsatisfactory	The HVACR installation in the above building contains violations of the Arkansas State Mechanical Code as listed below. You are directed to change this installation to meet the minimum requirements of the State Code within days. Failure to change the installation will result in			
HVACR License	charges against your license, or other legal action. If there is any question, contact the Local / Area			
Gas Supply	Inspector immediately.			
Power Supply				
Supply duct	(Comments)			
Return Duct				
Ref. Piping	Inspect Air handler, humidifier, and short duct run. Appears to meet code			
Insulation	requirements at this time.			
Drain Piping				
Duct Sealed				
Duct Insulation				
<pre> Equip. Access Low Vol. Wiring</pre>				
Other Piping				
Pipe Supports				
Pipe Welds				
Air Filter				
Venting				
Proper Clearance				
Thermostat				
Trash / Debris				
Plenums				
Equip. Listing				
Equip. Location				
Equip. Supports				
Fire Dampers				
Smoke Detectors Combustion Air				
Ventilation Air				
Other (explain)				
Approved				
Dis-Approved				
Owner:				
Owner: Email:		Contractor Email:		
HVACR Contractor:				
State HVACR Inspector: Don Brannendon.brannen@Arkansas.GovPh. # 501-69				Ph. # 501-690-6192