

Boring Log No. B-3

Graphic Log	Location: See Exploration Plan Latitude: 34.8999° Longitude: -92.1427°	Depth (Ft.)	Water Level Observed	Sample Type	Recovery (%)	Field Test Results	Water Content (%)	Atterberg Limits LL-PL-PI	Percent Fines
	Depth (Ft.)								
	0.5	TOPSOIL							
		SANDY FAT CLAY (CH), dark brown to reddish brown, medium stiff to stiff							
			5		10	2-4-4 N=8	18.7	59-17-42	70.7
					14	4-4-5 N=9	39.9		
					14	4-4-4 N=8	41.7		
					8	5-6-6 N=12	35.4		
	8.5	FAT CLAY (CH), light gray, stiff							
			10		18	4-4-6 N=10	37.1	93-25-68	96.0

Facilities | Environmental | **Geotechnical** | Materials

Boring Log No. B-4

Location: 'See Exploration Plan Latitude: 34.8999° Longitude: -92.1424°		Atterberg Limits LL-PL-PI		Percent Fines				
Graphic Log	Depth (ft.)	Water Level Observed	Sample Type	Recovery (%)	Field Test Results	Water Content (%)		
	0.5							
	TOPSOIL FAT CLAY WITH SAND (CH) , dark brown to reddish brown, medium stiff to stiff							
	10			10	1-2-3 N=5	21.0		
	10			10	3-4-6 N=10	18.4		
	14			14	5-6-6 N=12	23.6		
	14.0			20	4-3-4 N=7	27.4	74-20-54	87.4
color transition to light gray below about 8.5 feet								
	16			16	3-3-4 N=7	38.1		
	18.6			12	7-38-50/1"	19.3		
Boring Terminated at 18.6 Feet				4	50/1"	9.6		
See Exploration and Testing Procedures for a description of field and laboratory procedures used and additional data (if any). See Supporting Information for explanation of symbols and abbreviations. Samples obtained using a 2" O.D. split spoon sampler		Water Level Observations No free water observed during augering		Drill Rig 546 Track Hammer Type Automatic Driller EBS				
Notes		Advancement Method Solid Stem Augers		Logged by DA Boring Started 01-06-2026 Boring Completed 01-06-2026				
		Abandonment Method Boring backfilled with auger cuttings upon completion.						

Facilities | Environmental | **Geotechnical** | Materials

FOR INFORMATION ONLY